THE LAUREN, A CONDOMINIUM SUPPLEMENTARY INFORMATION ON FUTURE MAJOR REPAIRS AND REPLACEMENTS DECEMBER 31, 2013 (UNAUDITED)

The Association had a replacement reserve study conducted by Reserve Advisors, Inc. during 2011 to estimate the remaining useful lives and the replacement costs of the components of common property. Replacement costs were based on the estimated costs to repair or replace the common property components at the date of the study. The estimated replacement costs presented below do not take into account the effects of inflation between the date of the study and the date the components will require repair or replacement.

The following has been extracted from the Association's replacement reserve study and presents significant information about the components of common property.

	2011 Estimated	
	Remaining	2011
	Useful	Estimated
	Life	Replacement
Component	(Years)	Cost
Exterior Elements	0-9	\$ 1,298,125
Interior Elements	0-17	646,200
Building Services Elements	0-25	2,208,400
Property Site Elements	0-15	217,555
Pool Elements	14	115,000
Garage Elements	7-19	114,775
Annual Contingency	1	300,000
Reserve Study Elements	2	4,200